

Hardware

	2026-1					2026-2				2026-3				2026-4				2026-5				2026-6				
	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	
Hardware																										
Move the notes from "warehouse" to redmine.																										
Create BOM creator script with warehouse (...)																										
Cablemeter																										
PCB: missing info for 3V																										
CANBuz																										
Create sinewave for DAC/DMA																										
Helios																										
Check I2C pullups																										
Driver board: No level shifter for I2C																										
Calculate voltage-divider for "Enable" (...)																										
Eval-RTC: Strange behaviour when battery (...)																										
Resistor between BAT and "Enable" is (...)																										
mainSwitch																										
PCB routing problem																										
Switch via photodiode																										
Power supply on CANBus is very poor																										
Wakeup-Button is not working																										
Verseion 2: more power, RTC																										
LM25056: Current calculated wrongly																										
Minutnik																										
Buttons do not fit																										
Minutnik elnk																										
Does UART-RX need Pullu por -down?																										
Minutnik elnk - v0.2.x																										
consumption tests completely (...)																										
Yellow and red LEDs are quite (...)																										
Power consumption too high																										

Are both wakeups working correctly NUC64DEBUG use bigger buttons NUC64DEBUG - v0.3.x BOOT0 Button pulls pin low instead (...) Rufa Footprint fuer thermocouple-Kupplung (...) Introduce more noise filtering One pin is completely missing Housing sensemux Bringup HW v0.2.x	
--	--